

The Xtendo-HUB hub is a new fix to an old problem. The old problem is that the concrete septic tank baffle has deteriorated and it's time to be replaced with plastic sanitary tee. How do you fit a new sanitary tee when the pipe does not extend into the tank? The Xtendo-HUB is an internal male hub connector. The male end glues into the ID of Sch-40 or SDR-3034 4" pipe. The other end of the Xtendo-HUB is a Sch-40 hub. A desired length of pipe is glued into the hub which allows you to connect the sanitary tee. Problem solved - job finished.

